


LOC I-TPA 110.3	APP CRS 184°	Rwy ldg TDZE Apt Elev	8300 26 26
---------------------------	------------------------	-----------------------------	---------------------------------------

ILS RWY 18L (CAT II)

TAMPA INTL (TPA)



<p>Simultaneous approaches authorized with Rwy 18R. RADAR REQUIRED.</p>	<p>ALSIF-2</p>	<p>MISSED APPROACH: Climb to 600 then climbing left turn to 2800 via heading 150° and PIE R-132 to GIBBS INT/PIE 29.3 DME and hold.</p>
	<p>ARR 126.45</p>	<p>ATIS 128.475</p>

<p>TAMPA APP CON 118.5 290.3</p>	<p>TAMPA TOWER 119.5 269.4</p>	<p>GND CON 121.7 269.4</p>	<p>CLNC DEL 133.6</p>
---	---	---------------------------------------	----------------------------------



SE-3, 22 OCT 2009 to 19 NOV 2009

SE-3, 22 OCT 2009 to 19 NOV 2009



CATEGORY II ILS - SPECIAL AIRCREW & AIRCRAFT CERTIFICATION REQUIRED