

CARGO-SIX DEPARTURE (CARGO6•CARGO)

SHL-511 [USN]

DEPARTURE ROUTE DESCRIPTION

(Continued)

ALL RWY: Cross the Departure End of Runway at or above 35' AGL.

TAKE-OFF RWY 3L/R: Climb heading 030° until crossing BZA R-135, turn left direct BZA VORTAC, then.....

TAKE-OFF RWY 8: Turn left direct BZA VORTAC, then.....

TAKE-OFF RWY 17, 21L/R: Climb heading 210° to join and arc S on the BZA 14 mile arc to join and fly BZA R-170 to BZA VORTAC, then.....

TAKE-OFF RWY 26: Turn right direct BZA VORTAC, then.....

TAKE-OFF RWY 35: Direct BZA VORTAC, then.....

Fly BZA R-305 to CARGO. Cross SALUD at or above 3600. Cross CARGO at or above 5000.

BARD TRANSITION(CARGO6•BZA): At CARGO, turn left to join and fly BZA R-290 to BZA VORTAC.

BLYTHE TRANSITION(CARGO6•BLH): At CARGO, turn right to join and fly BLH R-175 to BLH VORTAC.

HEEDS TRANSITION(CARGO6•HEEDS): At CARGO, turn left to join and fly BLH R-180 to HEEDS. Cross HEEDS at or above 8000.

IMPERIAL TRANSITION(CARGO6•IPL): At CARGO, turn left to join and fly IPL R-050 to IPL VORTAC.

SW-4, 22 OCT 2009 to 19 NOV 2009

SW-4, 22 OCT 2009 to 19 NOV 2009

CARGO-SIX DEPARTURE (CARGO6•CARGO)