

HILO, HAWAII

AL-756 (FAA)



# VOR/DME or TACAN-A HILO INTL (ITO) (PHTO)

VORTAC ITO <b>116.9</b> Chan <b>116</b>	APP CRS <b>145°</b>	Rwy Idg TDZE Apt Elev	<b>N/A</b> <b>N/A</b> <b>38</b>
---	------------------------	-----------------------------	---------------------------------------




**⚠** Circling not authorized south of Rwy 8-26.

MISSED APPROACH: Climbing left turn to 3000 via ITO R-079 to VEWES/5 DME and hold.

ATIS <b>126.4</b>	HILO APP CON <b>119.7 269.2</b>	HILO TOWER ★ <b>118.1 (CTAF) 263.1</b>	GND CON <b>121.9</b>
----------------------	------------------------------------	---	-------------------------



ELEV 38



CATEGORY	A	B	C	D	REIL Rwy 3 MIRL Rwy 3-21 HIRL Rwy 8-26
CIRCLING	500-1½ 462 (500-1½)			700-2 662 (700-2)	

HILO, HAWAII  
Amdt 7B 09071

19°43'N-155°03'W

# HILO INTL (ITO) (PHTO) VOR/DME or TACAN-A

PAC, 22 OCT 2009 to 17 DEC 2009

PAC, 22 OCT 2009 to 17 DEC 2009