


VORTAC RID 110.6 Chan 43	APP CRS 332°	Rwy Idg TDZE 1140 Apt Elev 1140
--	------------------------	---

VOR RWY 33
RICHMOND MUNI (RID)



<p>▼ Visibility reduction by helicopters NA. When local altimeter setting not received, use James M Cox Dayton Intl altimeter setting and increase all MDA 100 feet.</p> <p>▲ NA Increase S-33 Cat C, D visibility ¼ mile.</p>	<p>MISSED APPROACH: Climb to 2700 then left turn direct RID VORTAC and hold.</p>
--	---

AWOS-3 121.225	DAYTON APP CON 134.45 352.05	CLNC DEL 133.55	UNICOM 122.7 (CTAF) 📻
--------------------------	--	---------------------------	--



EC-2, 22 OCT 2009 to 19 NOV 2009

EC-2, 22 OCT 2009 to 19 NOV 2009



CATEGORY	A	B	C	D
S-33	1640-1	500 (500-1)	1640-1¼ 500 (500-1¼)	1640-1½ 500 (500-1½)
CIRCLING	1640-1	500 (500-1)	1640-1½ 500 (500-1½)	1700-2 560 (600-2)

LDIN Rwy 24 **📻**
MIRL Rwys 15-33 and 6-24 **📻**
REIL Rwys 6 and 24 **📻**