


| | | | |
|----------------------|------------------------|-----------------------------|--|
| LOM MW 223 | APP CRS 085° | Rwy Idg TDZE Apt Elev | N/A N/A 957 |
|----------------------|------------------------|-----------------------------|--|

NA If local altimeter setting not received, use James M Cox Dayton Intl altimeter setting and increase all MDAs 60 feet.




MISSED APPROACH: Climb to 2500, then climbing right turn to 3000 direct MW LOM and hold.

| | | | |
|------------------------|---|--------------------------|--|
| ASOS 118.375 | DAYTON APP CON 118.85 127.225 327.1 | CLNC DEL 119.4 | UNICOM 122.8 (CTAF) D |
|------------------------|---|--------------------------|--|



EC-2, 22 OCT 2009 to 19 NOV 2009

EC-2, 22 OCT 2009 to 19 NOV 2009



| | | | | | | | | | | |
|----------|--------|-------------|-------------------------|-------------------------|-------------------|------|------|------|------|------|
| CATEGORY | A | B | C | D | FAF to MAP 4.4 NM | | | | | |
| CIRCLING | 1480-1 | 523 (600-1) | 1520-1½ 563 (600-1½) | 1660-2¼ 703 (800-2¼) | Knots | 60 | 90 | 120 | 150 | 180 |
| | | | | | Min:Sec | 4:24 | 2:56 | 2:12 | 1:46 | 1:28 |