

LINDEN, MICHIGAN

AL-6232 (FAA)

# RNAV (GPS) RWY 9


LINDEN/ PRICE'S (9G2)

APP CRS	Rwy Idg	<b>3732</b>
<b>095°</b>	TDZE	<b>919</b>
	Apt Elev	<b>920</b>

**▽** Use Flint altimeter setting; when not received, use Howell altimeter setting. DME/DME RNP-0.3 NA.

**▲** NA MISSED APPROACH: Climb to 2900 direct TUKJU and hold.



FLINT ASOS <b>133.15</b>	FLINT APP CON * <b>118.8 257.9</b>	UNICOM <b>123.0 (CTAF) 0</b>
-----------------------------	---------------------------------------	---------------------------------



EC-1, 22 OCT 2009 to 19 NOV 2009

EC-1, 22 OCT 2009 to 19 NOV 2009

ELEV 920	Rwy 9 Idg 3732'
	Rwy 27 Idg 3200'



CATEGORY	A	B	C	D
LNAV MDA	1400-1	481 (500-1)		NA
CIRCLING	1460-1	540 (600-1)		NA

LINDEN, MICHIGAN  
Amdt 1 08185

42°48'N - 83°46'W

# RNAV (GPS) RWY 9

LINDEN/ PRICE'S (9G2)