



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RUNWAY 14: Climbing right turn via 340° heading and MEF NDB 269° bearing outbound to GNATS INT. Thence. . . .

TAKE-OFF RUNWAY 27: Climbing right turn via 285° heading and MEF NDB 269° bearing outbound to GNATS INT. Thence. . . .

TAKE-OFF RUNWAY 32: Climbing left turn via MEF NDB 269° bearing outbound to GNATS INT. Thence. . . .

. . . .via (transition) or (assigned route). Maintain 10,000' or assigned lower altitude.

COPPO TRANSITION (GNATS3.COPPO): From over GNATS INT via OED R-216 to OLECY INT, then via the OED 15 DME Arc to COPPO DME.

DREWS TRANSITION (GNATS3.DREWS): From over GNATS INT via the MEF NDB 269° bearing to MERLI INT, then via the OED 15 DME Arc to DREWS DME.

HANDY TRANSITION (GNATS3.HANDY): From over GNATS INT via the OED R-216 to OLECY INT, then via the OED 15 DME Arc to HANDY DME.

KOLER TRANSITION (GNATS3.KOLER): From over GNATS INT via MEF NDB 269° bearing to MERLI INT, then via RBG R-154 to KOLER INT.

MOURN TRANSITION (GNATS3.MOURN): From over GNATS INT via MEF NDB 269° bearing to MERLI INT, then via the OED 15 DME Arc to intercept OED R-333 to MOURN INT.

TALEM TRANSITION (GNATS3.TALEM): From over GNATS INT via OED R-216 to OLECY INT, then via the OED 15 DME Arc to intercept OED R-157 to TALEM DME.

NW-1, 22 OCT 2009 to 19 NOV 2009

NW-1, 22 OCT 2009 to 19 NOV 2009