

# RNAV (GPS) RWY 34L

MIDLAND INTL (MAF)







APP CRS <b>346°</b>	Rwy Idg TDZE Apt Elev	<b>9501</b> <b>2857</b> <b>2871</b>
------------------------	-----------------------------	---



GPS or RNP-0.3 required. DME/DME RNP-0.3 NA.  
Circling NA at night to Rwy 16L.

MISSED APPROACH: Climb to 5100 direct ADAYA and hold.

ATIS <b>126.8 235.975</b>	MIDLAND APP CON* <b>124.6 290.4</b>	MIDLAND TOWER * <b>118.7 (CTAF) 0273.45</b>	GND CON <b>121.9 348.6</b>	CLNC DEL <b>118.05 317.65</b>	UNICOM <b>122.95</b>
------------------------------	--	--	-------------------------------	----------------------------------	-------------------------



CATEGORY	A	B	C	D
LNAV MDA	3280-1	423 (500-1)	3280-1¼	423 (500-1¼)
CIRCLING	3340-1	469 (500-1)	3340-1½	3440-2
			469 (500-1½)	569 (600-2)

MIRL Rwy 4-22 and 16L-34R  
REIL Rwy 34L  
HIRL Rwy 10-28 and 16R-34L

SC-3, 22 OCT 2009 to 19 NOV 2009

SC-3, 22 OCT 2009 to 19 NOV 2009