

GLAMIS-SIX DEPARTURE (GLAMS6•CARGO)

YUMA, ARIZONA


 SHL-511 [USN]
 DEPARTURE ROUTE DESCRIPTION
 (CONTINUED)

ALL RWY: Cross the Departure End of Runway at or above 35' AGL.

TAKE-OFF RWY 3L/R: Climb heading 030° to NYL 4 DME, turn left heading 280° to BRYGG, then fly NYL R-317 to CARGO. Cross CARGO at or above 5000.

TAKE-OFF RWY 8, 35: Turn left direct BRYGG, then fly NYL R-317 to CARGO. Cross CARGO at or above 5000.

TAKE-OFF RWY 17, 21L/R and 26: Turn right direct PNOBB, then fly NYL R-317 to CARGO. Cross BRYGG at or above 3600. Cross CARGO at or above 5000.

BARD TRANSITION (GLAMS6 • BZA): At CARGO turn left to join and fly BZA R-290 to BZA VORTAC.

BLYTHE TRANSITION (GLAMS6 • BLH): At CARGO turn right to join and fly BLH R-175 to BLH VORTAC.

HEEDS TRANSITION (GLAMS6 • HEEDS): At CARGO turn left to join and fly BLH R-180 to HEEDS. Cross HEEDS at or above 8000.

IMPERIAL TRANSITION (GLAMS6 • IPL): At CARGO turn left to join and fly IPL R-050 to IPL VORTAC.

SW-4, 22 OCT 2009 to 19 NOV 2009

SW-4, 22 OCT 2009 to 19 NOV 2009

GLAMIS-SIX DEPARTURE (GLAMS6•CARGO)

YUMA, ARIZONA

YUMA MCAS/YUMA INTL (KNYL)