

HILO, HAWAII


AL-756 (FAA)

VOR-B
HILO INTL (ITO) (PHTO)

VORTAC ITO 116.9 Chan 116	APP CRS 259°	Rwy Idg TDZE Apt Elev N/A N/A 38
---	------------------------	--

<p>▼ Circling not authorized south of Rwy 8-26.</p>	<p>MISSED APPROACH: Climbing right turn to 3000 via ITO R-002 then direct to ITO VORTAC and hold.</p>
--	---

<p>ATIS 126.4</p>	<p>HILO APP CON 119.7 269.2</p>	<p>HILO TOWER ★ 118.1 (CTAF) 0 263.1</p>	<p>GND CON 121.9</p>
------------------------------	--	---	---------------------------------



HILO, HAWAII
Orig-B 09071

19°43'N-155°03'W

HILO INTL (ITO) (PHTO)
VOR-B

PAC, 22 OCT 2009 to 17 DEC 2009

PAC, 22 OCT 2009 to 17 DEC 2009