

ARRIVAL DESCRIPTION

FORT DODGE TRANSITION (FOD.RBA3): From over FOD VORTAC via FOD R-191 and RBA R-013 to RBA VOR/DME. Thence. . . .

OMAHA TRANSITION (OVR.RBA3): From over OVR VORTAC via OVR R-162 and RBA R-346 to RBA VOR/DME. Thence. . . .

PAWNEE CITY TRANSITION (PWE.RBA3): From over PWE VORTAC via PWE R-115 and RBA R-296 to RBA VOR/DME. Thence. . . .

LANDING KANSAS CITY INTL:

Rwys 1L/R: From over RBA VOR/DME via RBA R-137 to HUGGY INT then via heading 190°. Thence....

Rwys 19L/R: From over RBA VOR/DME via RBA R-137 to JUDAA INT then via heading 110°. Thence....

Rwys 9, 27: From over RBA VOR/DME via RBA R-137 to JUDAA INT. Thence...

LANDING CHARLES B. WHEELER DOWNTOWN (MKC):

Rwys 1, 3: From over RBA VOR/DME via RBA R-137 to HUGGY INT then via heading 190°. Thence...

Rwys 19, 21: From over RBA VOR/DME via RBA R-137 to JUDAA INT. Thence...

LANDING OLATHE/JOHNSON COUNTY EXECUTIVE (OJC) and OLATHE/ NEW

CENTURY AIRCENTER (IXD): From over RBA VOR/DME via RBA R-137 to HUGGY INT then via heading 190°. Thence...

ALL OTHER AIRPORTS: From over RBA VOR/DME via RBA R-137 to JUDAA INT. Thence...

. . . . Expect radar vector to final approach course.

NC-3, 22 OCT 2009 to 19 NOV 2009

NC-3, 22 OCT 2009 to 19 NOV 2009