



(CONTINUED FROM PRECEDING PAGE)

DEPARTURE ROUTE DESCRIPTION

Cross HAVTI at or above 4000. Cross HABAS at or above 6000. Cross CHINA at assigned altitude.

TAKE OFF RWY 14: Climbing right turn to intercept NID R-148 to CHINA. Cross HADOP at or above 6000. Cross CHINA at assigned altitude.

ALL RWYS: Max departure speed 250 KIAS until established on R-148. From CHINA, proceed via assigned transition or expect radar vectors to join assigned route.

EDWARDS TRANSITION (CHINA4•EDW): Via EDW R-027 to EDW. Expect radar vectors to join assigned route.

HECTOR TRANSITION (CHINA4•HEC): Via HEC R-280 to HEC.

SW-3, 22 OCT 2009 to 19 NOV 2009

SW-3, 22 OCT 2009 to 19 NOV 2009