



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RUNWAY 3: Climbing right turn heading 240° to intercept and track outbound on HOM R-200 to OLSON DME.

TAKE-OFF RUNWAY 21: Climb on runway heading to intercept and track outbound on HOM R-200 to OLSON DME.

AUGEY TRANSITION (OLSON2.AUGEY): From OLSON DME right turn to 260° heading and V321 to AUGHEY INT.

HOMER TRANSITION (OLSON2.HOM): From OLSON DME via HOM R-200 to HOM VOR/DME.

KENAI TRANSITION (OLSON2.ENA): From OLSON DME via HOM R-200 to HOM VOR/DME, then via HOM R-332 and ENA R-186 to ENA VOR/DME.

MALLT TRANSITION (OLSON2.MALLT): From OLSON DME right turn to 260° heading and V322 to MALLT INT.

SHUYA TRANSITION (OLSON2.SHUYA): From OLSON DME left turn to 130° heading and V438 to SHUYA INT.

AK, 22 OCT 2009 to 17 DEC 2009

AK, 22 OCT 2009 to 17 DEC 2009