

KODIAK FIVE DEPARTURE (OBSTACLE)



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RUNWAY 7: Climb via heading 074° to intercept ODK VOR/DME R-222 to ODK or 047° course to RWO NDB. Thence

TAKE-OFF RUNWAY 11: Climbing left turn to intercept ODK VOR/DME R-222 to ODK or 047° course to RWO NDB. Thence

TAKE-OFF RUNWAY 18: Climbing left turn to intercept ODK VOR/DME R-222 to ODK or 047° course to RWO NDB. Thence . . . , or for climb in visual conditions: cross Kodiak airport eastbound at or above 3100 to intercept ODK R-222 to ODK or 047° course to RWO NDB. Thence

TAKE-OFF RUNWAY 29: Climb in visual conditions direct ODK VOR/DME or RWO NDB (visual conditions must be maintained from takeoff until established over ODK VOR/DME or RWO NDB); cross ODK VOR/DME or RWO NDB at or above 2400 MSL, Thence

TAKE-OFF RUNWAY 36: Climbing right turn via heading 120° to intercept ODK VOR/DME R-222 to ODK or 047° course to RWO NDB. Thence . . . , or for climb in visual conditions: cross Kodiak airport eastbound at or above 3100 to intercept ODK R-222 to ODK or 047° course to RWO NDB, Thence

. . . . Climb to 4000 via ODK VOR/DME R-015 or 015° bearing from RWO NDB. V357 proceed on course, all others climbing left turn direct ODK VOR/DME or RWO NDB and then proceed on course.

AK, 22 OCT 2009 to 17 DEC 2009

AK, 22 OCT 2009 to 17 DEC 2009