



LOC/DME RWY 28L

HAYWARD EXECUTIVE (HWD)


LOC/DME I-HWD 111.5	APP CRS 287°	Rwy Idg TDZE Apt Elev	5018 47 47
Chan 52			

⚠ Circling not authorized north of Rwy 10L-28R. MISSED APPROACH: Climb to 2000 direct OAK VORTAC and hold.

ATIS 126.7	NORCAL APP CON 124.4 351.8	HAYWARD TOWER* 120.2 (CTAF) 0 257.8	GND CON 121.4	CLNC DEL 128.05	UNICOM 122.95
----------------------	--------------------------------------	---	-------------------------	---------------------------	-------------------------



ELEV	47	Rwy 10R Idg 4878'	Rwy 28L Idg 5018'		
MIRL Rwy 10R-28L					
MIRL Rwy 10L-28R					
REIL Rws 10R and 28L					
Knots	60	90	120	150	180
Min:Sec					



CATEGORY	A	B	C	D
S-28L	400-1	353 (400-1)		400-1¼ 353 (400-1¼)
CIRCLING	540-1	493 (500-1)	540-1½ 493 (500-1½)	600-2 553 (600-2)

SW-2, 22 OCT 2009 to 19 NOV 2009

SW-2, 22 OCT 2009 to 19 NOV 2009