

DEPARTURE ROUTE DESCRIPTION

When entering controlled airspace, fly assigned heading and altitude to appropriate route.

LONGVIEW TRANSITION (HUBB6.GGG): From over TTT VOR/DME via TTT R-094 to ROCKK INT, then via GGG R-279 to GGG VORTAC.

PARIS TRANSITION (HUBB6.PRX): From over TTT VOR/DME via TTT R-064 to ECKEY INT, then via PRX R-221 to PRX VOR/DME.

QUITMAN TRANSITION (HUBB6.UIM): From over TTT VOR/DME via TTT R-084 to SOLDO INT, then via UIM R-261 to UIM VOR/DME.

SOLDO TRANSITION (HUBB6.SOLDO): (ATC assigned.) From over TTT VOR/DME via TTT R-084 to SOLDO INT.

TEXARKANA TRANSITION (HUBB6.TXK): From over TTT VOR/DME via TTT R-074 to SHERO INT, then via TXK R-244 to TXK VORTAC.

TYLER TRANSITION (HUBB6.TYR): From over TTT VOR/DME via TTT R-094 to ROCKK INT, then via TYR R-303 to TYR VOR/DME.

TAKE-OFF OBSTACLES:

Rwy 17:

Multiple trees beginning 190' from departure end of runway, 178' right of centerline, up to 66' AGL/665' MSL.

Building 371' from departure end of runway, 261' left of centerline, 14' AGL/643' MSL.

Rwy35:

Tree 1,242' from departure end of runway, 806' right of centerline, 63' AGL/692' MSL.

SC-2, 22 OCT 2009 to 19 NOV 2009

SC-2, 22 OCT 2009 to 19 NOV 2009