



DEPARTURE ROUTE DESCRIPTION

When entering controlled airspace, fly assigned heading and altitude to appropriate route.

LONGVIEW TRANSITION (HUBB6.GGG): From over TTT VOR/DME via TTT R-094 to ROCKK INT, then via GGG R-279 to GGG VORTAC.

PARIS TRANSITION (HUBB6.PRX): From over TTT VOR/DME via TTT R-064 to ECKEY INT, then via PRX R-221 to PRX VOR/DME.

QUITMAN TRANSITION (HUBB6.UIM): From over TTT VOR/DME via TTT R-084 to SOLDO INT, then via UIM R-261 to UIM VOR/DME.

SOLDO TRANSITION (HUBB6.SOLDO): (ATC assigned.) From over TTT VOR/DME via TTT R-084 to SOLDO INT.

TEXARKANA TRANSITION (HUBB6.TXK): From over TTT VOR/DME via TTT R-074 to SHERO INT, then via TXK R-244 to TXK VORTAC.

TYLER TRANSITION (HUBB6.TYR): From over TTT VOR/DME via TTT R-094 to ROCKK INT, then via TYR R-303 to TYR VOR/DME.

TAKE-OFF OBSTACLES:

Rwy 31:

Multiple trees beginning 1,133' from departure end of runway, 479' left of centerline, up to 40' AGL/541' MSL.

Trees 886' from departure end of runway, 637' right of centerline, 35' AGL/536' MSL.

Multiple poles beginning 5,613' from departure end of runway, 1,171' right of centerline, up to 101' AGL/661' MSL.

SC-2, 22 OCT 2009 to 19 NOV 2009

SC-2, 22 OCT 2009 to 19 NOV 2009