

COLUMBUS, OHIO

AL-5958 (FAA)

NDB RWY 4

COLUMBUS/BOLTON FIELD (TZR)





LOM BU 230	APP CRS 038°	Rwy Idg 5500
		TDZE 905
		Apt Elev 905

⚠ When local altimeter setting not received use Port Columbus altimeter setting and increase all MDA 60 feet and increase S-4 Cat C/D visibility ¼ mile.



MISSED APPROACH: Climb to 1400 then climbing right turn to 2700 direct BU LOM and hold.

AWOS-3 135.925	COLUMBUS APP CON 132.3 279.6	BOLTON TOWER★ 128.1 (CTAF) 0	GND CON 121.8
--------------------------	--	--	-------------------------



CATEGORY	A	B	C	D
S-4	1400-¾ 495 (500-¾)			1400-1¼ 495 (500-1¼)
CIRCLING	1420-1	515 (600-1)	1420-1½ 515 (600-1½)	1460-2 555 (600-2)

FAF to MAP 5.4 NM					
Knots	60	90	120	150	180
Min:Sec	5:24	3:36	2:42	2:10	1:48

COLUMBUS, OHIO
Amdt 7 09015

39°54'N - 83°08'W

COLUMBUS/BOLTON FIELD (TZR)
NDB RWY 4

EC-2, 22 OCT 2009 to 19 NOV 2009

EC-2, 22 OCT 2009 to 19 NOV 2009