

LINDEN, NEW JERSEY


AL-6291 (FAA)

GPS-A
LINDEN (LDJ)

APP CRS 039°	Rwy ldg TDZE Apt Elev	N/A N/A 23
------------------------	-----------------------------	---------------------------------------

<p>▽ Obtain local altimeter setting on CTAF, when not received, use Newark Liberty Intl altimeter setting.</p> <p>▲ NA</p>	<p>MISSED APPROACH: Climbing left turn to 2000 direct VANER WP and hold.</p>
--	--


AWOS-3 124.025	NEW YORK APP CON 135.35 379.9	CLNC DEL 128.35	UNICOM 123.0 (CTAF) ①
--------------------------	---	---------------------------	--



NE-2, 22 OCT 2009 to 19 NOV 2009

NE-2, 22 OCT 2009 to 19 NOV 2009

RADAR REQUIRED



ELEV 23	Rwy 9 ldg 3677'	Rwy 27 ldg 3594'
Fly Visual 088° 2.1 NM		
MIRL Rwy 9-27 ①		
REIL Rwy 9 and 27		

CATEGORY	A	B	C	D
CIRCLING	620-2½ 597 (600-2½)			NA
NEWARK ALTIMETER SETTING MINIMUMS				
CIRCLING	640-2½ 617 (700-2½)			NA

LINDEN, NEW JERSEY
Orig-A 08157

40°37'N - 74°15'W

LINDEN (LDJ)
GPS-A