

QUINCY, FLORIDA

AL-6775 (FAA)




VORTAC SZW <b>117.5</b> Chan <b>122</b>	APP CRS <b>283°</b>	Rwy Idg TDZE Apt Elev <b>N/A</b> <b>N/A</b> <b>221</b>
---	------------------------	---

**VOR/DME-A**  
QUINCY MUNI (2J9)

**NA** Use Tallahassee Rgnl altimeter setting; when not received use Bainbridge, GA altimeter setting and increase all MDA 20 feet.

MISSED APPROACH: Climbing left turn to 2100 direct SZW VORTAC and hold.

TALLAHASSEE RGNL ASOS <b>119.45 239.25</b>	TALLAHASSEE APP CON * <b>128.7 254.3</b>	UNICOM <b>122.7</b> (CTAF)
---	---	-------------------------------



CATEGORY	A	B	C	D
CIRCLING	840-1	619 (700-1)	860-1 <sup>3</sup> / <sub>4</sub> 639 (700-1 <sup>3</sup> / <sub>4</sub> )	NA

QUINCY, FLORIDA  
Amdt 1 09183

30° 36' N - 84° 33' W

QUINCY MUNI (2J9)  
**VOR/DME-A**

SE-3, 22 OCT 2009 to 19 NOV 2009

SE-3, 22 OCT 2009 to 19 NOV 2009