



DEPARTURE ROUTE DESCRIPTION

When entering controlled airspace fly assigned heading and altitude to appropriate route.

GUTHRIE TRANSITION (KING7.GTH): (For all aircraft landing within Lubbock terminal area or proceeding westbound via V-18 to GTH VORTAC). From over TTT VOR/DME via TTT R-274 to FUZ VORTAC, then via FUZ R-261 to RUWLO INT, then via MQP R-265 to BEKLE INT, then via GTH R-146 to GTH VORTAC.

MILLSAP TRANSITION (KING7.MQP): (For all aircraft overflying the MQP VORTAC westbound via V-18 or direct). From over TTT VOR/DME via TTT R-250 to PODDE INT, then via MQP R-081 to MQP VORTAC.

PODDE TRANSITION (KING7.PODDE): (ATC assigned.) From over TTT VOR/DME via TTT R-250 to PODDE INT.

WICHITA FALLS TRANSITION (KING7.SPS): (For all aircraft landing within the Wichita Falls terminal area or overflying the SPS VORTAC). From over TTT VOR/DME via TTT R-285 to MUZZO INT, then via SPS R-148 to SPS VORTAC.

SC-2, 22 OCT 2009 to 19 NOV 2009

SC-2, 22 OCT 2009 to 19 NOV 2009